137 Harley Street, London W1G 6BG Tel: +44 20 7034 3070 Fax: +44 20 7034 3071 Email: fmfcertification@fetalmedicine.com

Wolfgang Moroder Via Rezia, 64 Ortisei BZ 39046 Italy

Aug 24, 2015 FMF ID: 17976

## Measurement of uterine artery PI

Dear Wolfgang Moroder,

Thank you for submitting your logbook of 3 images. I examined each image for the following criteria: sagittal section, angle of insonation angle less than 30 degrees, velocity more than 60 cm/s, and sample volume 2.0 mm (see table below).

	Image number		
Criteria	1	2	3
Sagittal section	4	<b>✓</b>	<b>✓</b>
Insonation angle < 30°	<b>✓</b>	<b>✓</b>	<b>✓</b>
Velocity > 60 cm/s	×	<b>✓</b>	<b>✓</b>
Sample Volume 2.0 mm	4	<b>✓</b>	<b>✓</b>

Legend: ✓ = pass × = fail -- = not possible to assess

Your images are satisfactory. Your software license will include the assessment of **uterine artery flow** in the risk calculation for preeclampsia and your name will appear on the list of sonographers certified for assessment of uterine artery flow.

Best wishes,

Olga Torres Khoury